

Inspection Report

Permit Holder: ConocoPhillips Canada Resources Corp.
Inspection: 2026-2313
Inspection Date: 2026-07-08
Inspection Outcome: Inspected

Inspection Comment:

- * Travel to COP HZ BLUEBERRY 14-23- 088-25 site sign in site orientation.
- * Meet and greet with site supervisors. discuss operations and delay in startup.
- * discuss Explosive storage, pressure testing procedures and documentation
- * due to current operations a full site inspection was not conducted.
- * Plan to return to site once frac operations start up.
- * sign out leave location.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100118245
Well ID: 55942
Well Name: COP HZ BLUEBERRY M14-23-088-25
Location: DLS: M14-23-088-25

Authorized by BCER