

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-2314
Inspection Date: 2026-07-08
Inspection Outcome: Inspected

Inspection Comment:

Site 03-06-081-14 was inspected at or about 1215 hours, it was 20 & windy/sunny. The following was included in the inspection:
Access and signage: Signage clear and legible
Site: Wellsite clean and no vegetation concerns
Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locked, no concerns
Meter/separator buildings: locks, leaks, caps, vents, - no concerns
Chemical tanks: leaks, grounds, caps, - no concerns
Note: Landowner attended - appeared upset that hunters were accessing area.
Explained my role and responsibility - he left area.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100021199
Well ID: 10769
Well Name: TOURMALINE DOE 03-06-081-14
Location: DLS: 03-06-081-14

Permit: 100053779
Facility ID: 00003798
Facility Name: TOURMALINE DOE 03-06-081-14 001
Facility Type: Compressor Dehydrator
Location: DLS: 03-06-081-14

Permit Holder: Tourmaline Oil Corp.

Authorized by BCER