

Inspection Report

Permit Holder: ARC Resources Ltd.
Inspection: 2026-2316
Inspection Date: 2026-07-09
Inspection Outcome: Inspected

Inspection Comment:

Site 01-36-078-15 was inspected at or about 1115 hours, it was 17 & overcast.
The following was included in the inspection:
Access and signage: Signage clear and legible, rut, culverts at entrance~ 50% each side see photos
Site: Wellsite clean and no vegetation concerns
Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locks unobserved due to wrapping
Meter/separator buildings: locks, leaks, caps, vents, - no concerns
Chemical tanks: leaks, grounds, caps, - no concerns
Riser & pig stations: chains, grounds, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100019437
Well ID: 10047
Well Name: ARGRES KILKERRAN 01-36-078-15
Location: DLS: 01-36-078-15

Permit: 100070874
Well ID: 26203
Well Name: ARGRES HZ DAWSON A01-36-078-15
Location: DLS: A01-36-078-15

Permit: 100070915
Well ID: 26212
Well Name: ARGRES HZ DAWSON B01-36-078-15
Location: DLS: B01-36-078-15

Permit: 100070916
Well ID: 26213
Well Name: ARGRES HZ DAWSON C01-36-078-15
Location: DLS: C01-36-078-15

Permit: 100070874
Facility ID: 00024569
Facility Name: ARCRES HERITAGE 01-36-078-15 002
Facility Type: Well Facility
Location: DLS: 01-36-078-15

Permit: 100070915
Facility ID: 00024571
Facility Name: ARCRES HERITAGE 01-36-078-15 003
Facility Type: Well Facility
Location: DLS: 01-36-078-15

Permit: 100070916
Facility ID: 00024572
Facility Name: ARCRES HERITAGE 01-36-078-15 004
Facility Type: Well Facility
Location: DLS: 01-36-078-15

Permit Holder: ARC Resources Ltd.

Authorized by BCER