

Inspection Report

Permit Holder: ARC Resources Ltd.
Inspection: 2026-2317
Inspection Date: 2026-07-09
Inspection Outcome: Inspected

Inspection Comment:

Site 15-29-078-14 was inspected at or about 1150 hours, it was 17 & overcast.
The following was included in the inspection:
Access and signage: Signage clear and legible, culvert damage at 209 Rd and entrance (pics)
Site: Wellsite clean and no vegetation concerns
Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locked, no concerns
Meter/separator buildings: locks, leaks, caps, vents, - no concerns
Chemical tanks: leaks, grounds, caps, - no concerns
Riser & pig stations: chains, grounds, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100073516
Well ID: 27264
Well Name: ARGRES HZ DAWSON A15-29-078-14
Location: DLS: A15-29-078-14

Permit: 100076754
Well ID: 28661
Well Name: ARGRES HZ DAWSON B15-29-078-14
Location: DLS: B15-29-078-14

Permit: 100076754
Facility ID: 00025749
Facility Name: ARGRES HERITAGE 15-29-078-14 003
Facility Type: Well Facility
Location: DLS: 15-29-078-14

Permit Holder: ARC Resources Ltd.



Inspection Number: 2026-2317
Inspection Date: 2026-07-09

Letter ID: L2603320
Letter Date: 2026-07-10

Authorized by BCER