

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2364
Inspection Date: 2026-07-09
Inspection Outcome: Inspected

Inspection Comment:

Access and access signage inspected. Access rutted.

Pad clean.

Inspect well. No SCV flow observed. Barricades present. Signage clear and legible. Meter building inspected.

Amount on well is in override position. Called area lead, who had operator attend site same day to correct. See pictures.

400bbl tank and containment. Separator building. Pig barrel inspected.

Chem tanks inspected.

Associated pipeline well vegetated.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100069401
Well ID: 25654
Well Name: OVV HZ BRASSEY B- 096-C/093-P-10
Location: NTS: B- 096-C/093-P-10

Permit: 100069401
Facility ID: 00024265
Facility Name: OVV HERITAGE B-096-C/093-P-10 001
Facility Type: Well Facility
Location: NTS: B- 096-C/093-P-10

Authorized by BCER