

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2376
Inspection Date: 2026-07-09
Inspection Outcome: Inspected

Inspection Comment:

Access and access signage inspected.

Pad clean.

Inspect well. No SCV flow observed. Barricades present. Signage clear and legible. Critical valves locked. Meter building inspected.

Separator building inspected.

400BBL tanks and containment inspected.

Pig barrel inspected.

Chem tanks inspected.

Associated pipeline well vegetated.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100076003
Well ID: 28251
Well Name: OVV CRP ET AL HZ BRASSEY C- 084-D/093-P-10
Location: NTS: C- 084-D/093-P-10

Permit: 100076003
Facility ID: 00025577
Facility Name: OVV HERITAGE C-084-D/093-P-10 001
Facility Type: Well Facility
Location: NTS: C- 084-D/093-P-10

Permit: 100076003
Road Number: 02280
Segment IDs (Location): 001 (From NTS: D- 084-D/093-P-10 To NTS: C- 084-D/093-P-10)



Inspection Number: 2026-2376
Inspection Date: 2026-07-09

Letter ID: L2603406
Letter Date: 2026-07-13

Authorized by BCER