

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-2399
Inspection Date: 2026-07-09
Inspection Outcome: Inspected

Inspection Comment:

WA# 20761 - July 9, 2026: 12:12 hrs. on site.

Wellhead: Suspended Status, flowline is disconnected with all valve handles being chained and locked.

KERMIT most recent gas production date: 2025-02 (Suspended Status).

Signage is compliant with standards with exception of a faded flammable safety symbol which has been weathered/sunscald and requires updating/replacing.

Well Building: Out of Service - disconnected flowlines - Suspended Status.

Storage: no storage tanks devices are being used

Flowlines: flowlines are disconnected at wellhead to well building and to pipeline (Deactivated Status). Pig barrel closure safety chain is not attached to PAV and low point drain ball valve is missing a bull plug.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100051850
Well ID: 20761
Well Name: TOURMALINE BLACK B- 082-B/094-H-12
Location: NTS: B- 082-B/094-H-12

Permit: 100051373
Pipeline Project ID: 000016414
Segment IDs (Location): 1 (From NTS: B- 082-B/094-H-12 To NTS: C- 084-B/094-H-12), 2 (From NTS: C- 084-B/094-H-12 To NTS: B- 095-B/094-H-12)

Authorized by BCER



Inspection Number: 2026-2399
Inspection Date: 2026-07-09

Letter ID: L2603440
Letter Date: 2026-07-14