

Inspection Report

Permit Holder: Tourmaline Oil Corp.

Inspection: 2026-2405

Inspection Date: 2026-07-09

Inspection Outcome: Inspected

Inspection Comment:

WA# 22104 - July 9, 2026: 12:42 hrs. on site.

Wellhead: SCVA ball valve is in the open position, Suspended Status, flowline is disconnected with all valves handles being chained & locked.

Signage is compliant with standards with exception of a faded flammable safety symbol which has been weathered/sunscald and requires updating/replacing.

Well Building: Out of Service - disconnected flowlines - Suspended Status.

Storage: no storage tanks devices are being used

Flowlines: flowlines are disconnected at wellhead to well building and to pipeline (Deactivated Status). Pig barrel closure chain is attached to PAV.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100057203

Well ID: 22104

Well Name: TOURMALINE ET AL BLACK C- 045-B/094-H-12

Location: NTS: C- 045-B/094-H-12

Permit: 100057203

Facility ID: 00022517

Facility Name: TOURMALINE BLACKCREEK C-045-B/094-H-12 001

Facility Type: Well Facility

Location: NTS: C- 045-B/094-H-12

Permit: 100054240

Pipeline Project ID: 000017264

Segment IDs (Location): 2 (From NTS: C- 045-B/094-H-12 To NTS: A- 056-B/094-H-12)



Inspection Number: 2026-2405
Inspection Date: 2026-07-09

Letter ID: L2603447
Letter Date: 2026-07-15

Authorized by BCER