

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-2406
Inspection Date: 2026-07-09
Inspection Outcome: Inspected

Inspection Comment:

WA# 25842 - July 9, 2026: 12:47 hrs. on site.

Wellhead: SCVA ball valve handle is in the open position, no LEL measured, and no flow observed. Suspended Status, flowline is disconnected with all valves handles were either 1) chained & locked or 2) removed.

Signage is compliant with standards.

Well Building: Out of Service - disconnected flowlines - Suspended Status.

Storage: double wall tank on a metal stand, grounded, SDS labels present - "Out of Service".

Flowlines: flowlines are disconnected at wellhead to well building and to pipeline (Deactivated Status).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100069984
Well ID: 25842
Well Name: TOURMALINE ET AL BLACK C- 046-B/094-H-12
Location: NTS: C- 046-B/094-H-12

Permit: 100069984
Facility ID: 00024368
Facility Name: TOURMALINE BLACKCREEK C-046-B/094-H-12 001
Facility Type: Well Facility
Location: NTS: C- 046-B/094-H-12

Permit: 100070169
Pipeline Project ID: 000021877
Segment IDs (Location): 1 (From NTS: C- 046-B/094-H-12 To NTS: C- 045-B/094-H-12)



Inspection Number: 2026-2406
Inspection Date: 2026-07-09

Letter ID: L2603448
Letter Date: 2026-07-15

Authorized by BCER