

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-2407
Inspection Date: 2026-07-09
Inspection Outcome: Inspected

Inspection Comment:

WA# 20684 - July 9, 2026: 12:51 hrs. on site.

Wellhead: SCVA ball valve handle is in the open position, Suspended Status, flowline is disconnected with all valve handles being either: 1) chained & locked or 2) removed.

Signage is compliant with standards with exception of a faded flammable safety symbol which has been weathered/sunscald and requires updating/replacing in the near future.

Well Building: Out of Service - disconnected flowlines - Suspended Status.

Storage: no storage tanks devices are being used

Flowlines: flowlines are disconnected at wellhead to well building and to pipeline (Deactivated Status).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100051778
Well ID: 20684
Well Name: TOURMALINE ET AL BLACK D- 047-B/094-H-12
Location: NTS: D- 047-B/094-H-12

Permit: 100053712
Pipeline Project ID: 000017266
Segment IDs (Location): 1 (From NTS: D- 047-B/094-H-12 To NTS: C- 057-B/094-H-12)

Permit: 100054240
Pipeline Project ID: 000017264
Segment IDs (Location): 1 (From NTS: A- 056-B/094-H-12 To NTS: D- 047-B/094-H-12)



Inspection Number: 2026-2407
Inspection Date: 2026-07-09

Letter ID: L2603449
Letter Date: 2026-07-15

Authorized by BCER