

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-2408
Inspection Date: 2026-07-09
Inspection Outcome: Inspected

Inspection Comment:

WA# 20761 - July 9, 2026: 12:58 hrs. on site.

Wellhead: SCVA ball valve handle is in the open position, Suspended Status, flowline is disconnected with all valve handles as chained & locked.

Signage is compliant with standards with exception of a faded flammable safety symbol which has been weathered/sunscald and requires updating/replacing in the near future.

Well Building: Out of Service - disconnected flowlines - Suspended Status.

Storage: double wall tank on metal stand within plastic containment, SDS labels present, "Out of Service".

Flowlines: flowlines are disconnected at wellhead to well building and to pipeline (Deactivated Status).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100052565
Well ID: 20721
Well Name: TOURMALINE BLACK C- 079-B/094-H-12
Location: NTS: C- 079-B/094-H-12

Permit: 100052201
Pipeline Project ID: 000016787
Segment IDs (Location): 1 (From NTS: C- 079-B/094-H-12 To NTS: B- 098-B/094-H-12)

Authorized by BCER