

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-2409
Inspection Date: 2026-07-09
Inspection Outcome: Inspected

Inspection Comment:

WA# 10233 - July 9, 2026: 13:07 hrs. on site.

Wellhead: SCVA ball valve is in the open position, Suspended Status, flowline is disconnected with all valve handles being either chained & locked/removed.

Signage is compliant with standards with exception of a faded flammable safety symbol which has been weathered/sunscald and requires updating/replacing in the near future.

Well Building: Out of Service - disconnected flowlines - Suspended Status.

Storage: single wall tank (1x) on metal stand within plastic containment, drain plug in place, SDS labels present, grounded - "Out of Service".

Flowlines: flowlines are disconnected at wellhead to well building and to pipeline (Deactivated Status).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100019695
Well ID: 10233
Well Name: TOURMALINE ET AL CONROY D- 038-B/094-H-12
Location: NTS: D- 038-B/094-H-12

Permit: 100028616
Pipeline Project ID: 000009324
Segment IDs (Location): 1 (From NTS: D- 038-B/094-H-12 To NTS: B- 094-J/094-H-05)

Permit: 100035397
Pipeline Project ID: 000011219
Segment IDs (Location): 1 (From NTS: C- 097-B/094-H-12 To NTS: D- 038-B/094-H-12)



Inspection Number: 2026-2409
Inspection Date: 2026-07-09

Letter ID: L2603451
Letter Date: 2026-07-15

Authorized by BCER