

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-2411
Inspection Date: 2026-07-09
Inspection Outcome: Inspected

Inspection Comment:

WA# 11033 - July 9, 2026: 13:23 hrs. on site.

Wellhead: SCVA ball valve is in the open position, Suspended Status, flowline is disconnected with all valves handles being chained & locked.

Signage is compliant with standards.

Well Building: Out of Service - disconnected flowlines - Suspended Status.

Storage: double wall tank on metal stand, SDS labels present, and grounded - "Out of Service".

Flowlines: flowlines are disconnected at wellhead to well building and to pipeline (Deactivated Status).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100070829
Well ID: 25843
Well Name: TOURMALINE ET AL BLACK A-A093-J/094-H-05
Location: NTS: A-A093-J/094-H-05

Permit: 100070829
Facility ID: 00024369
Facility Name: TOURMALINE BLACKCREEK A-093-J/094-H-05 002
Facility Type: Well Facility
Location: NTS: A- 093-J/094-H-05

Permit: 100028616
Pipeline Project ID: 000009324
Segment IDs (Location): 11 (From NTS: A- 093-J/094-H-05 To NTS: B- 094-J/094-H-05)

Permit: 100059015
Pipeline Project ID: 000019123
Segment IDs (Location): 4 (From NTS: C- 082-J/094-H-05 To NTS: A- 093-J/094-H-05)



Inspection Number: 2026-2411
Inspection Date: 2026-07-09

Letter ID: L2603453
Letter Date: 2026-07-15

Authorized by BCER