

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2414

Inspection Date: 2026-07-14

Inspection Outcome: Inspected

Inspection Comment:

Site B-27-H/93-I-15 was inspected at or about 0940 hours, it was 15 & sunny.

The following was included in the inspection:

Access and signage: Signage clear and legible

Site: Wellsite clean and no vegetation concerns

Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locked, no concerns

Meter/separator buildings: locks, leaks, caps, vents, - one of the two buildings was not entered- unable to open

Chemical tanks: leaks, grounds, caps, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100044747

Well ID: 18372

Well Name: CNRL N GRIZZLY B- 027-H/093-I-15

Location: NTS: B- 027-H/093-I-15

Permit: 100044747

Facility ID: 00020851

Facility Name: CNRL GRIZZLYNORTH B-027-H/093-I-15 001

Facility Type: Well Facility

Location: NTS: B- 027-H/093-I-15

Permit Holder: Canadian Natural Resources Limited

Authorized by BCER