

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-2429

Inspection Date: 2026-07-14

Inspection Outcome: Inspected

Inspection Comment:

Signage no concerns.

All SCV's no venting observed.

Wet meter cabinets no concerns.

Shutdown isolation valves are sealed.

Actuators no concerns.

Sand separators no concerns.

5 chemical tanks with secondary containment no concerns.

Chemical injection systems no concerns.

Test separator no concerns.

Water pipeline riser building no concerns.

Propane tank is bonded to ground.

Pigging area no concerns.

Generator/instrument air building no concerns.

All plugs and caps in place.

No other concerns identified at time of site inspection.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100111468

Well ID: 41089

Well Name: PETRONAS HZ BLUEBERRY A- 060-D/094-A-13

Location: NTS: A- 060-D/094-A-13

Permit: 100113860
Well ID: 42490
Well Name: PETRONAS HZ BLUEBERRY A-A060-D/094-A-13
Location: NTS: A-A060-D/094-A-13

Permit: 100113860
Well ID: 42491
Well Name: PETRONAS HZ BLUEBERRY A-B060-D/094-A-13
Location: NTS: A-B060-D/094-A-13

Permit: 100113860
Well ID: 42492
Well Name: PETRONAS HZ BLUEBERRY A-C060-D/094-A-13
Location: NTS: A-C060-D/094-A-13

Permit: 100113860
Well ID: 42493
Well Name: PETRONAS HZ BLUEBERRY A-D060-D/094-A-13
Location: NTS: A-D060-D/094-A-13

Permit: 100113860
Well ID: 42494
Well Name: PETRONAS HZ BLUEBERRY A-E060-D/094-A-13
Location: NTS: A-E060-D/094-A-13

Permit: 100113860
Well ID: 42495
Well Name: PETRONAS HZ BLUEBERRY A-F060-D/094-A-13
Location: NTS: A-F060-D/094-A-13

Permit: 100117692
Facility ID: 00027907
Facility Name: PETRONAS BLUEBERRY A-060-D/094-A-13 001
Facility Type: Well Facility
Location: NTS: A- 060-D/094-A-13

Authorized by BCER