

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-2477
Inspection Date: 2026-07-16
Inspection Outcome: Inspected

Inspection Comment:

c-A76-H well is Suspended.

Wellhead disconnected from flowline, blinds installed. Wellhead valves chained and locked.

Sign and surface casing vent compliant.

Chem tanks removed from location.

Building compliant.

Pipeline valves in the closed position.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100039028
Well ID: 16622
Well Name: CANLIN CLARKE C-A076-H/094-J-10
Location: NTS: C-A076-H/094-J-10

Permit: 100033942
Pipeline Project ID: 000010813
Segment IDs (Location): 1 (From NTS: C- 076-H/094-J-10 To NTS: A- 081-G/094-J-10)

Authorized by BCER