

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-2479
Inspection Date: 2026-07-16
Inspection Outcome: Inspected

Inspection Comment:

a-81-G well is Suspended.

Wellhead disconnected from flowline, blinds installed. Wellhead valves chained and locked.

Sign and surface casing vent compliant.

Chem tanks removed from location.

Building compliant.

Sales P/L disconnected and blinds installed.

Comment:

1. 1) Scentless Chamomile observed on access road across from wellhead.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100011806
Well ID: 07371
Well Name: CANLIN CLARKE A- 081-G/094-J-10
Location: NTS: A- 081-G/094-J-10

Permit: 100011806
Facility ID: 00019009
Facility Name: CANLIN CLARKE LAKE A-081-G/094-J-10 001
Facility Type: Well Facility
Location: NTS: A- 081-G/094-J-10

Permit: 100012059
Pipeline Project ID: 000005021
Segment IDs (Location): 1 (From NTS: A- 081-G/094-J-10 To NTS: D- 072-G/094-J-10)

Permit: 100033942
Pipeline Project ID: 000010813
Segment IDs (Location): 1 (From NTS: C- 076-H/094-J-10 To NTS: A- 081-G/094-J-10)

Permit: 100042647
Pipeline Project ID: 000013213
Segment IDs (Location): 1 (From NTS: A- 081-G/094-J-10 To NTS: C- 072-G/094-J-10)

Authorized by BCER