

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-2482
Inspection Date: 2026-07-16
Inspection Outcome: Inspected

Inspection Comment:

Well is abandoned.

Well building and flowlines in place. Building compliant.

P/L disconnected and blinds installed.

Chem tanks removed.

No invasive plants observed.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100012334
Well ID: 07566
Well Name: CANLIN CLARKE A- 083-G/094-J-10
Location: NTS: A- 083-G/094-J-10

Permit: 100012798
Pipeline Project ID: 000005145
Segment IDs (Location): 1 (From NTS: A- 083-G/094-J-10 To NTS: D- 072-G/094-J-10)

Permit: 100030561
Pipeline Project ID: 000009821
Segment IDs (Location): 1 (From NTS: A- 083-G/094-J-10 To NTS: A- 083-G/094-J-10)

Permit: 100042117
Pipeline Project ID: 000013100
Segment IDs (Location): 1 (From NTS: A- 083-G/094-J-10 To NTS: C- 072-G/094-J-10), 2 (From NTS: C- 072-G/094-J-10 To NTS: A- 083-G/094-J-10)



Inspection Number: 2026-2482
Inspection Date: 2026-07-16

Letter ID: L2603545
Letter Date: 2026-07-17

Authorized by BCER