

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-2484
Inspection Date: 2026-07-16
Inspection Outcome: Inspected

Inspection Comment:

c-69-H well is Suspended.

Wellhead disconnected from flowline, blinds installed. Wellhead valves chained and locked.

Sign and surface casing vent compliant.

Chem tanks removed from location.

Building compliant.

Pipeline valves in the closed position.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100028286
Well ID: 13413
Well Name: CANLIN CLARKE C- 069-H/094-J-10
Location: NTS: C- 069-H/094-J-10

Permit: 100029576
Pipeline Project ID: 000009517
Segment IDs (Location): 1 (From NTS: C- 069-H/094-J-10 To NTS: C- 072-G/094-J-10)

Permit: 100064611
Pipeline Project ID: 000021030
Segment IDs (Location): 1 (From NTS: C- 058-H/094-J-10 To NTS: C- 069-H/094-J-10)



Inspection Number: 2026-2484
Inspection Date: 2026-07-16

Letter ID: L2603547
Letter Date: 2026-07-17

Authorized by BCER