

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-2486
Inspection Date: 2026-07-16
Inspection Outcome: Inspected

Inspection Comment:

a-74-G well is Suspended.

Wellhead disconnected from flowline, blinds installed. Wellhead valves chained and locked.

Sign and surface casing vent compliant.

Chem tank in place but empty and disconnected and capped inside well building.

Building compliant.

Pipeline valves in the closed position.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100014565
Well ID: 08226
Well Name: CANLIN ET AL CLARKE A- 074-G/094-J-10
Location: NTS: A- 074-G/094-J-10

Permit: 100109292
Facility ID: 00027071
Facility Name: CANLIN CLARKELAKE A-074-G/094-J-10 002
Facility Type: Well Facility
Location: NTS: A- 074-G/094-J-10

Permit: 100015741
Pipeline Project ID: 000005972
Segment IDs (Location): 1 (From NTS: A- 074-G/094-J-10 To NTS: A- 074-G/094-J-10)

Permit: 100033905

Pipeline Project ID: 000010808

Segment IDs (Location): 2 (From NTS: A- 075-G/094-J-10 To NTS: A- 074-G/094-J-10)

Authorized by BCER