

## Inspection Report

Permit Holder: ARC Resources Ltd.  
Inspection: 2026-2491  
Inspection Date: 2026-07-16  
Inspection Outcome: Inspected

### Inspection Comment:

- \* Travel to ARCRES HZ DAWSON CREEK G14-36-078-15, sign in site orientation.
- \* Meet with site supervisors review documents and discuss operations.
- \* Currently drilling.
- \* Conduct walk around and visual inspection with site supervisors.
- \* Discuss inspection with supervisors. no concerns upon completing this inspection.
- \* sign out return to Dawson Creek.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100116106  
Well ID: 45055  
Well Name: ARCRES HZ DAWSON CREEK H14-36-078-15  
Location: DLS: H14-36-078-15

---

Authorized by BCER