

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2516
Inspection Date: 2026-07-16
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100060354
Well ID: 22905
Well Name: OVV ECOG HZ KELLY D- 026-J/093-P-01
Location: NTS: D- 026-J/093-P-01

Permit: 100060355
Well ID: 22906
Well Name: OVV ECOG HZ KELLY D-A026-J/093-P-01
Location: NTS: D-A026-J/093-P-01

Permit: 100060354
Facility ID: 00022854
Facility Name: OVV DEEPBASIN D-026-J/093-P-01 001
Facility Type: Well Facility
Location: NTS: D- 026-J/093-P-01

Permit: 100060355
Facility ID: 00022855
Facility Name: OVV DEEPBASIN D-026-J/093-P-01 002
Facility Type: Well Facility
Location: NTS: D- 026-J/093-P-01

Authorized by BCER