

Inspection Report

Permit Holder: Cenovus Energy Inc.
Inspection: 2026-2527
Inspection Date: 2026-07-16
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) and secondary containment and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100005763
Well ID: 04057
Well Name: CVE ENERGY ET AL CUTBANK D- 093-A/093-P-08
Location: NTS: D- 093-A/093-P-08

Permit: 100005763
Facility ID: 00018729
Facility Name: CVE ENERGY CUTBANK D-093-A/093-P-08 001
Facility Type: Well Facility
Location: NTS: D- 093-A/093-P-08

Authorized by BCER