

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2530

Inspection Date: 2026-07-15

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-wellhead valves chained and locked. Flowline is disconnected from the wellhead.

Pumpjack remains in place connected to the polish rod. No SCVF.

-lease covered in vegetation.

-separator and tank, PJ, chem tank and piling/piping remain in place.

-access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100022849

Well ID: 11473

Well Name: CNRL ET AL RIGEL B- 023-A/094-A-15

Location: NTS: B- 023-A/094-A-15

Permit: 100069127

Facility ID: 00005723

Facility Name: CNRL RIGEL B-023-A/094-A-15 001

Facility Type: Battery Site

Location: NTS: B- 023-A/094-A-15

Permit: 100036976

Pipeline Project ID: 000011625

Segment IDs (Location): 1 (From NTS: B- 023-A/094-A-15 To NTS: D- 013-A/094-A-15)

Authorized by BCER