

Inspection Report

Permit Holder: ConocoPhillips Canada Resources Corp.

Inspection: 2026-2531

Inspection Date: 2026-07-16

Inspection Outcome: Inspected

Inspection Comment:

Signage no concerns

SCV on all wells no venting observed, B6-27-88-24 well has BCER accepted burst plate installed.

Shutdown isolation valves are car sealed.

Actuators no concerns.

Separator buildings no concerns.

Sand separators no concerns.

Chemical injections systems no concerns.

2 chemical tanks with secondary containment in place no concerns.

E-House/Instrument Air building no concerns.

Generator building no concerns.

Fuel gas heater building no concerns.

Line heater no concerns.

Pigging area no concerns.

All plugs and caps in place.

No other concerns identified at time of site inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100104394

Well ID: 36587

Well Name: COP HZ INGA NORTH 05-27-088-24

Location: DLS: 05-27-088-24

Permit: 100104394
Well ID: 36588
Well Name: COP HZ INGA NORTH A05-27-088-24
Location: DLS: A05-27-088-24

Permit: 100104394
Well ID: 36589
Well Name: COP HZ INGA NORTH B05-27-088-24
Location: DLS: B05-27-088-24

Permit: 100104394
Well ID: 36590
Well Name: COP HZ INGA NORTH C05-27-088-24
Location: DLS: C05-27-088-24

Permit: 100104394
Well ID: 36591
Well Name: COP HZ INGA NORTH D05-27-088-24
Location: DLS: D05-27-088-24

Permit: 100104394
Well ID: 36592
Well Name: COP HZ INGA NORTH E05-27-088-24
Location: DLS: E05-27-088-24

Permit: 100104394
Well ID: 36593
Well Name: COP HZ INGA NORTH 06-27-088-24
Location: DLS: 06-27-088-24

Permit: 100104394
Well ID: 36594
Well Name: COP HZ INGA NORTH A06-27-088-24
Location: DLS: A06-27-088-24

Permit: 100104394
Well ID: 36595
Well Name: COP HZ INGA NORTH B06-27-088-24
Location: DLS: B06-27-088-24

Permit: 100118469
Well ID: 49782
Well Name: COP HZ INGA NORTH C06-27-088-24
Location: DLS: C06-27-088-24

Permit: 100118469
Well ID: 49783
Well Name: COP HZ INGA NORTH D06-27-088-24
Location: DLS: D06-27-088-24

Permit: 100118469
Well ID: 49784
Well Name: COP HZ INGA NORTH E06-27-088-24
Location: DLS: E06-27-088-24

Permit: 100118469
Well ID: 49785
Well Name: COP HZ INGA NORTH F06-27-088-24
Location: DLS: F06-27-088-24

Permit: 100110620
Facility ID: 00027158
Facility Name: COP INGA NORTH 05-27-088-24 001
Facility Type: Well Facility
Location: DLS: 05-27-088-24

Authorized by BCER