

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2538

Inspection Date: 2026-07-15

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-wellhead valves chained and locked. Flowline is disconnected from the wellhead.
PJ remains in place, no polish rod. All equipment remains in place ie: tanks, separator, flarestack, PJ.

-Vegetation growing up and around the wellhead. As per the Guidelines, a 10-meter radius must be kept free of vegetation.

-tanks marked as "cleaned 2024".

-No SCVF

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100014097

Well ID: 08062

Well Name: CNRL RIGEL A- 014-A/094-A-15

Location: NTS: A- 014-A/094-A-15

Permit: 100014097

Facility ID: 00019081

Facility Name: CNRL BUICKCREEK A-014-A/094-A-15 001

Facility Type: Well Facility

Location: NTS: A- 014-A/094-A-15

Permit: 100014192

Facility ID: 00001158

Facility Name: CNRL RIGEL A-014-A/094-A-15 002

Facility Type: Battery Site

Location: NTS: A- 014-A/094-A-15



Inspection Number: 2026-2538
Inspection Date: 2026-07-15

Letter ID: L2603607
Letter Date: 2026-07-17

Authorized by BCER