

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2540

Inspection Date: 2026-07-15

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-wellhead valve handles removed. Flowline is disconnected from the wellhead.
Equipment remains in place.

-the lease is covered in Foxtail Barley and there is no 10-meter radius around
the wellhead free of vegetation as per the Guidelines.

-There is a chunk of piping (8"?) lying at the tree line on the North end of the
lease that looks to have a fox or coyote den in it. I seen the pups going in and
out of the piece of piping.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100018727

Well ID: 09831

Well Name: CNRL RIGEL A- 026-A/094-A-15

Location: NTS: A- 026-A/094-A-15

Authorized by BCER