

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2560

Inspection Date: 2026-07-15

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-unable to inspect this site due to a beaver dam across PDR 143 (approximately km 23) making the road impassible approximately 3 km from lease. This is preventing me from getting to a few locations on my inspection list.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001668

Well ID: 01269

Well Name: CNRL ET AL CURRANT D- 037-C/094-A-16

Location: NTS: D- 037-C/094-A-16

Authorized by BCER