

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2564

Inspection Date: 2026-07-16

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-walked into location as the lease road is overgrown with vegetation.

-wellhead valves chained and locked. Flowline is disconnected from the wellhead.
No SCVF

-On lease is wellhead, meter box and chemical tank. At beginning of lease road is a separator and tank (labeled as "out of service").

-All equipment and wellhead are overgrown with vegetation approximately 4 feet high.

-signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100004166

Well ID: 03102

Well Name: CNRL ET AL PEEJAY A- 034-E/094-A-16

Location: NTS: A- 034-E/094-A-16

Authorized by BCER