

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2565

Inspection Date: 2026-07-16

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-wellhead valves chained and locked. Flowline is disconnected from the wellhead.
Pumpjack remains in place connected to the polish rod.

-No SCVF

-vegetation growing up and around the wellhead and equipment. No 10-meter radius
around wellhead as per the Guidelines.

-Part of the location sign is missing (1/2 half of location missing).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100002245

Well ID: 01690

Well Name: CNRL ET AL PEEJAY D- 034-E/094-A-16

Location: NTS: D- 034-E/094-A-16

Permit: 100010811

Facility ID: 00000398

Facility Name: CNRL PEEJAY D-034-E/094-A-16 001

Facility Type: Satellite Battery

Location: NTS: D- 034-E/094-A-16

Authorized by BCER