

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2567

Inspection Date: 2026-07-16

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-wellhead only, valves chained and locked. No SCVF

-There is vegetation growing up and around wellhead 4 feet high. There is no 10-meter radius free of vegetation around the wellhead as per the Guidelines. Vegetation on the access road is also 4 feet high.

-there is a chemical tank stand and a steel stair at the tree line on the side of the lease.

-signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001862

Well ID: 01394

Well Name: CNRL ET AL BULRUSH D- 089-F/094-A-16

Location: NTS: D- 089-F/094-A-16

Authorized by BCER