

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-2573

Inspection Date: 2026-07-20

Inspection Outcome: Inspected

Inspection Comment:

July 20, 2026: 13:30 hrs.

Wellhead: CASED wells (6x): SCV valve handle is in the open position: Client is monitoring and reporting SCVA condition to standards.

Signage is compliant to standards: client to consider posting/adding a flammable symbol/decal on placard at wellhead locations.

No other issues noted.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100118021

Well ID: 48829

Well Name: PETRONAS HZ CARIBOU B-C006-H/094-G-07

Location: NTS: B-C006-H/094-G-07

Permit: 100118021

Well ID: 48830

Well Name: PETRONAS HZ CARIBOU B-D006-H/094-G-07

Location: NTS: B-D006-H/094-G-07

Permit: 100118021

Well ID: 48831

Well Name: PETRONAS HZ CARIBOU B-E006-H/094-G-07

Location: NTS: B-E006-H/094-G-07

Permit: 100118021

Well ID: 48832

Well Name: PETRONAS HZ CARIBOU B-F006-H/094-G-07

Location: NTS: B-F006-H/094-G-07

Permit: 100118021

Well ID: 48833

Well Name: PETRONAS HZ CARIBOU C- 096-A/094-G-07

Location: NTS: C- 096-A/094-G-07

Permit: 100118021
Well ID: 48834
Well Name: PETRONAS HZ CARIBOU C-A096-A/094-G-07
Location: NTS: C-A096-A/094-G-07

Authorized by BCER