

Inspection Report

Permit Holder: South Peace Parkland Ltd.

Inspection: 2026-2574

Inspection Date: 2026-07-16

Inspection Outcome: Inspected

Inspection Comment:

Site 06-01-082-15 was inspected at or about 1015 hours, it was 24 & sunny. The following was included in the inspection:

Access and signage: Signage clear and legible

Site: Wellsite clean and no vegetation concerns

Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locked, no concerns

Meter/separator buildings: locks, leaks, caps, vents, - no concerns

Chemical tanks: leaks, grounds, caps, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100006978

Well ID: 04918

Well Name: SOUTH PEACE PARKLAND 06-01-082-15

Location: DLS: 06-01-082-15

Authorized by BCER