

Inspection Report

Permit Holder: South Peace Parkland Ltd.

Inspection: 2026-2577

Inspection Date: 2026-07-16

Inspection Outcome: Inspected

Inspection Comment:

Site A11-03-082-15 was inspected at or about 1055 hours, it was 24 & sunny.

The following was included in the inspection:

Access and signage: Signage clear and legible at entrance, gated

Site: Wellsite clean and no vegetation concerns

Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical

valves locked, possible hiss under wrapping below actuator - Operator aware

Meter/separator buildings: locks, leaks, caps, vents, - LELs detected at pipe

(picture) Operate aware and maintains it is part of the sewage system - breather pipe

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100016139

Well ID: 08825

Well Name: SOUTH PEACE ET AL PARKLAND A11-03-082-15

Location: DLS: A11-03-082-15

Permit Holder: South Peace Parkland Ltd.

Authorized by BCER