Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-2578
Inspection Date: 2026-07-22
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

14934 - July 21, 2026: 14:49 hrs. on site

KERMIT last gas production date: 2026-05 (Active Status): wellhead is connected to flowline, and pipeline.

Signage posted on requires a well site location identifier and a flammable safety symbol/decal at entrance to road.

Well Building: Cata-Dyne heater system vent lines are in place. ESD last service date 2024.

Storage: double wall metal tank (1x) on a metal stand, SDS labels present, and grounded.

Flowline: flowline control valves handles are in the open position and connected from well through facility to pipeline - “Active Status”.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100033083
Well ID: 14934
Well Name: CANLIN   LAPRISE C- 026-I/094-G-08
Location: NTS: C- 026-I/094-G-08

_____

Authorized by BCER