

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2581
Inspection Date: 2026-07-21
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100064058
Well ID: 23990
Well Name: OVV HZ SWAN C- 071-B/093-P-09
Location: NTS: C- 071-B/093-P-09

Permit: 100064059
Well ID: 23991
Well Name: OVV ECOG HZ SWAN C-A071-B/093-P-09
Location: NTS: C-A071-B/093-P-09

Permit: 100064060
Well ID: 23992
Well Name: OVV ECOG HZ SWAN C-B071-B/093-P-09
Location: NTS: C-B071-B/093-P-09

Permit: 100064061
Well ID: 23993
Well Name: OVV ECOG HZ SWAN C-C071-B/093-P-09
Location: NTS: C-C071-B/093-P-09

Permit: 100064062
Well ID: 23994
Well Name: OVV ECOG HZ SWAN C-D071-B/093-P-09
Location: NTS: C-D071-B/093-P-09

Permit: 100064058
Facility ID: 00023426
Facility Name: OVV HERITAGE C-071-B/093-P-09 001
Facility Type: Well Facility
Location: NTS: C- 071-B/093-P-09

Permit: 100064059
Facility ID: 00023427
Facility Name: OVV HERITAGE C-071-B/093-P-09 002
Facility Type: Well Facility
Location: NTS: C- 071-B/093-P-09

Permit: 100064060
Facility ID: 00023428
Facility Name: OVV HERITAGE C-071-B/093-P-09 003
Facility Type: Well Facility
Location: NTS: C- 071-B/093-P-09

Permit: 100064061
Facility ID: 00023429
Facility Name: OVV HERITAGE C-071-B/093-P-09 004
Facility Type: Well Facility
Location: NTS: C- 071-B/093-P-09

Permit: 100064062
Facility ID: 00023430
Facility Name: OVV HERITAGE C-071-B/093-P-09 005
Facility Type: Well Facility
Location: NTS: C- 071-B/093-P-09

Authorized by BCER