

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-2592

Inspection Date: 2026-07-20

Inspection Outcome: Inspected

Inspection Comment:

This inspection is for c-39-H, c-A39-H, c-B39-H, c-C39-H.

c-39, c-B39, c-C39 are Active.

c-A39 casing only.

All signs compliant.

Gas detector overranged on LEL from SCV at c-B39-H, consistent with October 2023 test results in IRIS. Closed containment tub positioned below c-B39 SCV outlet.

All meter cabinets complaint. All critical valves secured.

Last meter cal June 2024, last orifice plate inspection June 2026.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100082451

Well ID: 31529

Well Name: PETRONAS HZ CARIBOU C- 039-H/094-G-07

Location: NTS: C- 039-H/094-G-07

Permit: 100082452

Well ID: 31530

Well Name: PETRONAS HZ CARIBOU C-A039-H/094-G-07

Location: NTS: C-A039-H/094-G-07

Permit: 100082453

Well ID: 31531

Well Name: PETRONAS HZ CARIBOU C-B039-H/094-G-07

Location: NTS: C-B039-H/094-G-07

Permit: 100082454
Well ID: 31532
Well Name: PETRONAS HZ CARIBOU C-C039-H/094-G-07
Location: NTS: C-C039-H/094-G-07

Permit: 100079288
Facility ID: 00017987
Facility Name: PETRONAS CARIBOU D-040-H/094-G-07 001
Facility Type: Well Facility
Location: NTS: D- 040-H/094-G-07

Authorized by BCER