

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2598
Inspection Date: 2026-07-23
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100061367
Well ID: 23216
Well Name: OVV ECOG HZ SUNRISE 08-30-077-15
Location: DLS: 08-30-077-15

Permit: 100063551
Well ID: 23908
Well Name: OVV ECOG HZ SUNRISE A08-30-077-15
Location: DLS: A08-30-077-15

Permit: 100063552
Well ID: 23909
Well Name: OVV ECOG HZ SUNRISE B08-30-077-15
Location: DLS: B08-30-077-15

Permit: 100067999
Well ID: 25278
Well Name: OVV ECOG HZ SUNRISE C08-30-077-15
Location: DLS: C08-30-077-15

Permit: 100061367
Facility ID: 00023009
Facility Name: OVV HERITAGE 08-30-077-15 001
Facility Type: Well Facility
Location: DLS: 08-30-077-15

Permit: 100063551
Facility ID: 00023388
Facility Name: OVV HERITAGE 08-30-077-15 003
Facility Type: Well Facility
Location: DLS: 08-30-077-15

Permit: 100063552
Facility ID: 00023389
Facility Name: OVV HERITAGE 08-30-077-15 004
Facility Type: Well Facility
Location: DLS: 08-30-077-15

Permit: 100067999
Facility ID: 00024080
Facility Name: OVV HERITAGE 08-30-077-15 007
Facility Type: Well Facility
Location: DLS: 08-30-077-15

Authorized by BCER