

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2599
Inspection Date: 2026-07-23
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100061384
Well ID: 23316
Well Name: OVV ECOG HZ SUNRISE A10-20-077-15
Location: DLS: A10-20-077-15

Permit: 100061385
Well ID: 23317
Well Name: OVV ECOG HZ SUNRISE B10-20-077-15
Location: DLS: B10-20-077-15

Permit: 100067122
Well ID: 25103
Well Name: OVV ECOG HZ SUNRISE D10-20-077-15
Location: DLS: D10-20-077-15

Permit: 100067123
Well ID: 25104
Well Name: OVV ECOG HZ SUNRISE C10-20-077-15
Location: DLS: C10-20-077-15

Authorized by BCER