

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2601
Inspection Date: 2026-07-23
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100055398
Well ID: 21510
Well Name: OVV SUNRISE 10-20-077-15
Location: DLS: 10-20-077-15

Permit: 100055398
Facility ID: 00022265
Facility Name: OVV HERITAGE 10-20-077-15 001
Facility Type: Well Facility
Location: DLS: 10-20-077-15

Permit: 100061384
Facility ID: 00023060
Facility Name: OVV HERITAGE 10-20-077-15 003
Facility Type: Well Facility
Location: DLS: 10-20-077-15

Permit: 100061385
Facility ID: 00023061
Facility Name: OVV HERITAGE 10-20-077-15 004
Facility Type: Well Facility
Location: DLS: 10-20-077-15

Permit: 100067122
Facility ID: 00024009
Facility Name: OVV HERITAGE 10-20-077-15 008
Facility Type: Well Facility
Location: DLS: 10-20-077-15

Permit: 100067123
Facility ID: 00024010
Facility Name: OVV HERITAGE 10-20-077-15 009
Facility Type: Well Facility
Location: DLS: 10-20-077-15

Authorized by BCER