

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2604
Inspection Date: 2026-07-23
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW meet current regulations.

NOTE: Bull plug missing from needle valve on wing valve on 6-7-77-14 needs to be installed.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100048510
Well ID: 19598
Well Name: OVV ECOG SWAN 05-07-077-14
Location: DLS: 05-07-077-14

Permit: 100058723
Well ID: 22736
Well Name: OVV ECOG HZ SWAN A05-07-077-14
Location: DLS: A05-07-077-14

Permit: 100067215
Well ID: 25119
Well Name: OVV ECOG HZ SWAN 06-07-077-14
Location: DLS: 06-07-077-14

Permit: 100048510
Facility ID: 00021274
Facility Name: OVV HERITAGE 05-07-077-14 001
Facility Type: Well Facility
Location: DLS: 05-07-077-14

Permit: 100058723
Facility ID: 00022781
Facility Name: OVV HERITAGE 05-07-077-14 003
Facility Type: Well Facility
Location: DLS: 05-07-077-14

Permit: 100067215
Facility ID: 00024016
Facility Name: OVV HERITAGE 06-07-077-14 001
Facility Type: Well Facility
Location: DLS: 06-07-077-14

Authorized by BCER