

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2605
Inspection Date: 2026-07-23
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100059339
Well ID: 22793
Well Name: OVV ECOG SWAN C- 060-H/093-P-09
Location: NTS: C- 060-H/093-P-09

Permit: 100062107
Well ID: 23589
Well Name: OVV ECOG HZ SWAN C-A060-H/093-P-09
Location: NTS: C-A060-H/093-P-09

Permit: 100062108
Well ID: 23591
Well Name: OVV ECOG HZ SWAN C-B060-H/093-P-09
Location: NTS: C-B060-H/093-P-09

Permit: 100059339
Facility ID: 00022804
Facility Name: OVV HERITAGE C-060-H/093-P-09 001
Facility Type: Well Facility
Location: NTS: C- 060-H/093-P-09

Permit: 100062107
Facility ID: 00023213
Facility Name: OVV HERITAGE C-060-H/093-P-09 003
Facility Type: Well Facility
Location: NTS: C- 060-H/093-P-09

Permit: 100062108
Facility ID: 00023215
Facility Name: OVV HERITAGE C-060-H/093-P-09 004
Facility Type: Well Facility
Location: NTS: C- 060-H/093-P-09

Authorized by BCER