

Inspection Report

Permit Holder: VERMILION ENERGY INC.

Inspection: 2026-2606

Inspection Date: 2026-07-23

Inspection Outcome: Inspected

Inspection Comment:

Site 08-22-081-14 was inspected at or about 0930 hours, it was 17 °C & sunny.

The following was included in the inspection:

Access and signage: Signage clear and legible

Site: Wellsite clean and no vegetation concerns

Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locked, - Operator attended site to replace plug and to lock/ chain handles

Meter/separator buildings: locks, leaks, caps, vents, - no concerns

Chemical tanks: leaks, grounds, caps, - no concerns

Riser & pig stations: chains, grounds, - no concerns

Two marked out of service - comms building and produced tank

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100083215

Well ID: 31790

Well Name: VERMILION HZ MICA 08-22-081-14

Location: DLS: 08-22-081-14

Permit: 100101970

Well ID: 33137

Well Name: VERMILION HZ MICA A08-22-081-14

Location: DLS: A08-22-081-14

Permit: 100106069

Well ID: 37024

Well Name: VERMILION HZ MICA B08-22-081-14

Location: DLS: B08-22-081-14

Permit: 100102538

Facility ID: 00026372

Facility Name: VERMILION MICA 08-22-081-14 003

Facility Type: Well Facility

Location: DLS: 8-22-81-14

Permit Holder: VERMILION ENERGY INC.



Inspection Number: 2026-2606
Inspection Date: 2026-07-23

Letter ID: L2603702
Letter Date: 2026-07-24

Authorized by BCER