

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2607
Inspection Date: 2026-07-23
Inspection Outcome: Inspected

Inspection Comment:

- * Travel to Oviniv 13-16-80-17.
- * Sign in site orientation.
- * Meet with site supervisors. discuss operations currently rigging up Treeline 17.
- * Review documents. conduct limited inspection due to current operations.
- * Discuss inspection with supervisors, no concerns at this stage of operations.
- * sign out return to Dawson Creek.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100103766
Well ID: 34846
Well Name: OVV HZ SUNRISE M13-16-080-17
Location: DLS: M13-16-080-17

Authorized by BCER