

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2609
Inspection Date: 2026-07-23
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100053893
Well ID: 21209
Well Name: OVV ECOG SWAN B- 050-H/093-P-09
Location: NTS: B- 050-H/093-P-09

Permit: 100060782
Well ID: 23086
Well Name: OVV ECOG HZ SWAN B-B050-H/093-P-09
Location: NTS: B-B050-H/093-P-09

Permit: 100060795
Well ID: 23085
Well Name: OVV ECOG HZ SWAN B-A050-H/093-P-09
Location: NTS: B-A050-H/093-P-09

Permit: 100053893
Facility ID: 00022111
Facility Name: OVV HERITAGE B-050-H/093-P-09 001
Facility Type: Well Facility
Location: NTS: B- 050-H/093-P-09

Permit: 100060782
Facility ID: 00022947
Facility Name: OVV HERITAGE B-050-H/093-P-09 003
Facility Type: Well Facility
Location: NTS: B- 050-H/093-P-09

Permit: 100060795
Facility ID: 00022946
Facility Name: OVV HERITAGE B-050-H/093-P-09 004
Facility Type: Well Facility
Location: NTS: B- 050-H/093-P-09

Authorized by BCER