

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-2610
Inspection Date: 2026-07-23
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100022998
Well ID: 11484
Well Name: OVV SWAN B- 039-H/093-P-09
Location: NTS: B- 039-H/093-P-09

Permit: 100064731
Well ID: 24188
Well Name: OVV ECOG HZ SWAN B-A039-H/093-P-09
Location: NTS: B-A039-H/093-P-09

Permit: 100064732
Well ID: 24189
Well Name: OVV ECOG HZ SWAN B-B039-H/093-P-09
Location: NTS: B-B039-H/093-P-09

Permit: 100022998
Facility ID: 00019406
Facility Name: OVV SWANLAKE B-039-H/093-P-09 001
Facility Type: Well Facility
Location: NTS: B- 039-H/093-P-09

Permit: 100064731
Facility ID: 00023541
Facility Name: OVV HERITAGE B-039-H/093-P-09 003
Facility Type: Well Facility
Location: NTS: B- 039-H/093-P-09

Permit: 100064732
Facility ID: 00023542
Facility Name: OVV HERITAGE B-039-H/093-P-09 004
Facility Type: Well Facility
Location: NTS: B- 039-H/093-P-09

Authorized by BCER