

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-2619
Inspection Date: 2026-07-22
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- active electric pumpjack. No SCVF
- location sign is 300 meters away from wellsite at beginning of lease road.
- lease and access are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100003154
Well ID: 02369
Well Name: WHITECAP ET AL BOUNDARY 07-06-086-13
Location: DLS: 07-06-086-13

Authorized by BCER