

Inspection Report

Permit Holder: Whitecap Resources Inc.

Inspection: 2026-2627

Inspection Date: 2026-07-22

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-pumpjack inactive at time of inspection. Flowline is connected to the wellhead. Pumpjack connected to the polish rod and in place. Well shows production as recent as June 2026.

-No SCVF, but handle is missing on surface casing vent.

-location signage needs the sour symbol updated, as there is only a diamond shape hanging from the bottom of the sign but no symbol. No gas or oil analysis on file for this well, same as many other wells in this area.

-lease and access are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100000196

Well ID: 00152

Well Name: WHITECAP ET AL BOUNDARY 14-06-086-13

Location: DLS: 14-06-086-13

Authorized by BCER