

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-2672
Inspection Date: 2026-07-23
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-wellhead valves chained and locked. Flowline is disconnected from the wellhead.
Pumpjack remains in place disconnected.

-No SCVF

-lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001396
Well ID: 01074
Well Name: WHITECAP ET AL BOUNDARY 06-19-086-13
Location: DLS: 06-19-086-13

Authorized by BCER