

Inspection Report

Permit Holder: Enercapita Energy Ltd.
Inspection: 2026-2675
Inspection Date: 2026-07-23
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- active pumpjack with separator and tank.
- No SCVF
- lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100063680
Well ID: 23860
Well Name: ENERCAPITA BOUNDARY 13-21-086-13
Location: DLS: 13-21-086-13

Permit: 100063680
Facility ID: 00023361
Facility Name: ENERCAPITA BOUNDARYLAKE 13-21-086-13 001
Facility Type: Well Facility
Location: DLS: 13-21-086-13

Authorized by BCER